

January 14, 2014

Attention: To Whom it May Concern

RE: HERITAGE RESTORATION INC.

Heritage Restoration Inc. were awarded the contract to fully enclose, blast remove the existing interior and exterior coatings and recoat the interior and exterior of both the Alton and Mono Mills welded steel standpipes for Peel Region. The coating system specified was ICS-3 (a two coat system) on the interior and OCS-4 (a three coat system) on the exterior using an organic zinc-rich primer. There were miscellaneous steel repair, hatch repair and other improvements to both tanks. Heritage Restorations' crew and sub-contractors mobilized and executed the work with professionalism, and in a safe and timely manner.

The project manager and crew from Heritage worked closely with the Region, CIMA, and our third party inspection company to ensure that the work was completed with excellent quality, within schedule and with little impact on the environment or to the residents or businesses adjacent to the work sites.

We were impressed with how safe and organized Heritage Restoration were in completing their work and how responsive they were to providing clarification on any item when requested. The entire team from Heritage Restoration were friendly, cordial and diligent.

We would not hesitate recommending Heritage Restoration Inc. to any Owner requiring the same type of work to be completed.

Sincerely,

CIMA Canada Inc.



Mike Elliott, P.Eng.
Senior Project Manager
mike.elliott@cima.ca

ME
Encl.

Recommendation Letter 140114.docx